

Revision 1
List ID 62050

Title C. Proposed Contract Price

Item ID Description Amount in words Amount in figures

989165 The Proposed Contract Price is

List ID 62051

Title D. THE PROPOSED CONTRACT PRICE IS FURTHER SUBDIVIDED AS FOLLOWS: Unit Price Bid Form

Item ID	Item No.	Payment Clause No.	Est. Quantity	Units	items of Work	Unit Prices (Written in Words)	Unit Prices (Written in Currency)
989166	IIB.01	IIB.01		1 ALL	Allowance for Radios		30,000.00
989167	IIB.02	IIB.02		1 ALL	Allowance for Cones, Barricades, and Signs		25,000.00
989168	IIB.03	IIB.03		1 ALL	Allowance for Utility Locating Service		15,000.00
989169	G-003.01	G-003-5.1	2,600	TON	Soil Reuse at Out-Of-State Lined Landfill		
989170	G-003.02	G-003-5.1	2,600	TON	Soil Reuse at Lined Landfill		
989171	G-003.03	G-003-5.1	2,600	TON	Soil Recycling at Asphalt Batch Facility		
989172	C-100.01	C-100-14	1	LS	Contractor Quality Control Program (CQCP)		
989173	C-102.01	C-102-5.1	13	EACH	Drain Inlet Protectors		
989174	C-102.02	C-102-5.2	1,120	LF	Fiber Rolls		
989175	C-105	C-105-6	1	LS	Mobilization		
989176	P-101.01	P-101-5.1	17,200	SY	Pavement Milling, Variable Depth (0-4")		
989177	P-101.03	P-101-5.3	900	LF	Bituminous to Bituminous Joint Sawing and Sealing		
989178	P-101.04	P-101-5.4	300	CY	Bituminous Pavement Excavation		
989179	P-102.01	P-102-5.1	100	GALLON	Type 1A Crack Repair		
989180	P-102.02	P-102-5.2	700	LF	Type 1B Crack Repair		
989181	P-102.03	P-102-5.2	700	LF	Type 1C Crack Repair		
989182	P-102.04	P-102-5.2	700	LF	Type 1D Crack Repair		
989183	P-152.01	P-152-4.1	9,400	CY	Unclassified Excavation		
989184	P-154.01	P-154-5.1	3,000	CY	Subbase Course		
989185	P-209.01	P-209-5.1	3,700	CY	Crushed Aggregate Base Course		
989186	P-401.01	P-401-8.1	7,800	TON	Asphalt Surface Course		
989187	P-603.01	P-603-5.1	3,200	GALLON	Bituminous Tack Coat		
989188	P-620.01	P-620-5.1	8,100	SF	Initial Pavement Markings		
989189	P-620.02	P-620-5.1	8,100	SF	Final Pavement Markings		
989190	P-620.03	P-620-5.2	10	SF	Pavement Marking Removal		
989191	P-620.04	P-620-5.1	400	SF	Thermoplastic Pavement Markings		
989192	D-701.01	D-701-5.1	300	LF	12-Inch Class V RCP Storm Drain Pipe		
989193	D-701.02	D-701-5.2	150	LF	Removal of Existing Storm Drain Pipe		
989194	D-751.01	D-751-5.1	1	EACH	Manholes		
989195	D-751.02	D-751-5.1	3	EACH	Catch Basins		
989196	D-751.04	D-751-5.1	5	EACH	Frame and Grate (or Cover)		
989197	D-751.05	D-751-5.1	1	EACH	Frame and Grate (or Cover) Removed and Discarded		
989198	D-910.01	D-910-5.1	7	EACH	Structure Adjustment		
989199	T-905.01	T-905-5.1	24,300	SY	Seeding		
989200	T-905.02	T-905-5.2	300	CY	Topsoil (Obtained On-Site)		
989201	T-905.03	T-905-5.3	100	CY	Topsoil (Furnished from Off-Site)		
989202	L-100.01	L-100.01	1	ALL	Modifications to ALCMS Equipment		30,000.00
989203	L-108-5.1	L-108-5.1	16,700	LF	No. 8 AWG, 5 kV, 600V, L-824, Type C Cable, Color Coded, Installed in Trench, Duct Bank or Conduit		
989204	L-108-5.2	L-108-5.2	16,700	LF	No. 6 AWG, Color Coded, Insulated, Stranded Equipment Ground. Installed in Duct Bank or Conduit		
989205	L-108-5.3	L-108-5.3	4,900	LF	No. 6 AWG, Solid, Bare Copper Counterpoise Wire, Installed Above the Duct Bank or Conduit, Including Connections/Terminations		
989206	L-110-5.1	L-110-5.1	4,200	LF	Non-Encased Electrical Conduit, 1-Way 2-Inch		
989207	L-110-5.2	L-110-5.2	600	LF	Concrete Encased Electrical Conduit, 1-Way 2-Inch, Minimum 48-inch		
989208	L-110-5.3	L-110-5.3	100	LF	cover		
989209	L-115-5.1	L-115-5.1	4	EA	Electrical Handhole		
989210	L-115-5.2	L-115-5.2	3	EA	Existing Electrical Manhole/Junction Structure Elevation Adjustment		
989211	L-125-5.1	L-125-5.1	2	EA	Remove and Install Relocated L-861-T Taxiway Edge Light, Quartz, Elevated, On Owner Supplied Base Can		
989212	L-125-5.2	L-125-5.1	1	EA	Remove and Install Relocated L-861(L) Runway Edge Light, Quartz, Elevated, On Owner Supplied Base Can		
989213	L-125-5.3	L-125-5.1	1	EA	Remove and Install Relocated L-850C Semi-Flush Runway Edge Light, Quartz, Elevated, On Owner Supplied Base Can		
989214	L-125-5.4	L-125-5.1	32	EA	Remove Existing Quartz Taxiway Edge Light and Replace with New Owner Supplied LED Edge Light on Existing Base Can, Install New Owner Supplied Transformer		
989215	L-125-5.5	L-125-5.1	5	EA	Remove and Install Existing L-861-T Taxiway Edge Light and Base Can at New Grade		
989216	L-125-5.6	L-125-5.1	44	EA	Install Owner Supplied L-861(L) Taxiway Edge Light, LED, Elevated, On Owner Supplied Base Can		
989217	L-125-5.7	L-125-5.1	9	EA	Install Owner Supplied L-861-T Taxiway Edge Light, Quartz, Elevated, On Owner Supplied Base Can		
989218	L-125-5.8	L-125-5.1	1	EA	Remove Existing Guidance Sign and Foundation		
989219	L-125-5.9	L-125-5.1	1	EA	Remove and Install Relocated L-858 Airfield Guidance Sign On New Foundation, Install New Owner Supplied LED Conversion Kit		
989220	L-125-5.10	L-125-5.1	3	EA	Install Owner supplied L-858(L) Sign - Single/Double Face, LED, Size 3 - 2 Module, Furnish Foundation		
989221	L-125-5.11	L-125-5.1	1	EA	Install Owner supplied L-858(L) Sign - Single/Double Face, LED, Size 3 - 3 Module, Furnish Foundation		
989222	L-125-5.12	L-125-5.1	1	EA	Install Owner supplied L-858(L) Sign - Single/Double Face, LED, Size 3 - 4 Module, Furnish Foundation		