Inspection Frequency Change Request (BRI-8)



Bridge: 04671 Town: 3	33900 - GRISWOLI	D Carried:	CARROLL ROAD	Crossed: PACHAUG RIVER		
Structure Inventory Date (43) Structure Type: A) Material B) Design Type (45) Number of Spans (48) Length of Maximum Spans (49) Structure Length (41) Structure Operational Stru	3 - Steel 01 - Slab 00 3 pan 26 ft 0 87 ft 0	in in	(54) Min. Vert. Underclearance (29) ADT (66) Inventory Rating (64) Operating Rating Evaluation Code Year of Evaluation	N ref 0 ft 0 in 535 15 20 E - Evaluated 2017	(59) Superstructure(60) Substructure(61) Channel(62) Culvert	3 3 3 7 N
Scheduling Section Consultant Assignment: Access Equipment: Access Equipment Comments: Flagman: Inspection Scheduling Comments:	0 No railroad fl	If Yes Reason: ecify in comments lagman required				
Inspection Types Routine Fracture Critical Underwater Special Indepth Interim Joint Measurement	Frequency	Туре	Comments Bridge closed until	replacement.		
Creation Date: 05/31/2023		Created By: Lapierre,Theodore Approved By: Lapierre,Theodore				